


ZERO SETTING DEVICE



- With magnetic base
- To adjust the tools to the 0-position to determine the reference point of the machine spindle
- No feeler gauge or starting contact is needed
- Spring loaded setting face
- Mechanical zero-setting instrument for CNC machine centers
- Low spring force to prevent cutting tool from damage

Unit:mm

Code	Range	Graduation	Height	Remark
1122-9001	0-2	0.01	50	Magnetic base
1122-9002	0-2	0.01	100	Magnetic base with switch